

Work Order ID 69414 - 2



Tuesday, May 10, 2011 3:29:22 PM

Item ID: D350-721-045

Accept



Setup Start



Revision ID:

Stop



Item Name: Maintenance Step, LH

Start Date: 5/10/2011 Start Qty: 200

Required Date: 5/31/2011 Req'd Qty: 200

Cust Item ID:

Customer:

Reference:

Approvals:

Process Plan:

Date: 11-05-10 Tooling:

Date:

Run Start



QC:

Date: SPC (Y/N):

Date:

Stop



Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
--------------------------------	--------------------------	----------------------	---------	--------	--------------	---------------	---------------	------------------	----------------

Draw Nbr

Revision Nbr

IIN-D350-721

Rev b

100

0.00



DOCUMENT CONTROL

DC

Memo

0.00

Document Control

Photocopy bluefile and create labels per PPP D350-721-045 CHG001

8/10/14

Chf BG 11-5-12
②

110

0.00



Pick Kit

Packaging

Memo

0.00

Packaging

11/5/12 SP

120

0.00



QC4- 100% Inspect kits for completeness

QC

Memo

0.00

Quality Control

8/10/14

X1
LH

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Work Order ID 69414



Page 2

Tuesday, May 10, 2011 3:29:22 PM

Item ID: D350-721-045

Accept



Setup Start



Revision ID:

Stop



Item Name: Maintenance Step, LH

Start Date: 5/10/2011 Start Qty: 2.00



Cust Item ID:

Required Date: 5/31/2011 Req'd Qty: 2.00



Customer:

Reference:

Run Start



Approvals: Process Plan:

Date:

Tooling:

Date:

Stop



QC:

Date:

SPC (Y/N):

Date:

Sequence ID/
Work Center ID

Operation
Description

Set Up/
Run Hours

Tool ID

Tool #

Plan
Code

Accept
Qty

Reject
Qty

Reject
Number

Insp.
Stamp

130

0.00



Packaging

Packaging

Memo

0.00

Identify and pack for shipping as per PPP D350-721-045
Identify and Stock
Location: 22

Rev A

11/9/14

[Signature]

140

0.00



QC21- Final Inspection - Work Order Release

QC

Memo

0.00

Quality Control

11/9/14

MF 11-09-14

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Picklist Print

Tuesday, May 10, 2011 3:29:28 PM

Page 1

Work Order ID: 69414

Parent Item: D350-721-045

Parent Item Name: Maintenance Step, LH

Start Date: 5/10/2011

Required Date: 5/31/2011

Start Qty: 2.00

Required Qty: 2.00

Comments: IPP A 05.05.11 New Issue KJ/JLM
IPP B 07.10.10 removed D3436-041 EC verified by DD

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
---------------------------------	------------------------	---------------	-------------	---------------------	------------------	-----------------	--------------------	----------------	-------------	--------------	---------------	----------------	--------

AN4-16A  Bolt		Purchased	No			110	Each	186.0000	4	8		11/5/12	
---	--	-----------	----	--	--	-----	------	----------	---	---	--	---------	--

Location

Loc Qty

Loc Code

ST358

186

116400

86

117514

100

AN960-416  Washer	NAS1149F0463P	Purchased	No			110	Each	0.0000	8	16		11/16/12	
---	---------------	-----------	----	--	--	-----	------	--------	---	----	--	----------	--

D3436-043  Step LH		Manufactured	No			110	Each	0.0000	1	2		11/16/12	
--	--	--------------	----	--	--	-----	------	--------	---	---	--	----------	--

MS20365-428  NUT		Purchased	No			110	Each	53.0000	4	8		11/16/12	
--	--	-----------	----	--	--	-----	------	---------	---	---	--	----------	--

Location

Loc Qty

Loc Code

ST315

53

116391

53

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

6.0 PARTS LIST

Qty -011	Qty -041	Qty -043	Qty -045	Qty -046	PART NUMBER	DESCRIPTION
X					D350-721-011	BASKET CLAMP KIT
	X				D350-721-041	LIGHTWEIGHT HELI- UTILITY-BASKET™
		X			D350-721-043	LIGHTWEIGHT HELI-UTILITY-BASKET™, SHORT VERSION
			X		D350-721-045	MAINTENANCE STEP, LH
				X	D350-721-046	MAINTENANCE STEP, RH
	1				D3324-041	BASKET BASE ASSEMBLY
	1				D3325-041	BASKET LID ASSEMBLY
		1			D3326-041	BASKET BASE ASSEMBLY
		1			D3327-041	BASKET LID ASSEMBLY
	2	2			D2022-101	SPACER
3	3	3			D2230-1	LUG
4	4	4			D2230-3	CLAMP
	1	1			D2332-041	PROP ASSEMBLY
	1	1			D2530	HANDLE ASSEMBLY
	2	2			D2535	SPRING
	2	2			D2537	BUSHING
8	8	8			D2732-030	RUBBER CUSHION
	2	2			D2931	BUMPER
	1	1			D3338-1	LUG
	2	2			D3350-041	STRUT
	1	1			D3351-1	LABEL
			1	1	D3436-041	CLAMP
			1		D3436-043	LH STEP
				1	D3436-044	RH STEP
	2	2			AN3-16A	BOLT
	2	2			AN4-7A	BOLT
	2	2			AN4-12A	BOLT
	4	4			AN4-14A	BOLT
8	8	8			AN4-15A	BOLT
			4	4	AN4-16A	BOLT
	1	1			AN4-20A	BOLT
	1	1			AN4-22A	BOLT
	4	4			AN5-17A	BOLT
			8	8	AN960-416	WASHER
16	30	30			AN960JD416	WASHER
	2	2			AN960JD416L	WASHER
	4	4			AN960JD516	WASHER
	2	2			AN960JD8	WASHER
	4	4			AN970-4	WASHER
			4	4	MS20365-428	NUT
	2	2			MS20600AD4W3	RIVET
	2	2			MS21042L3	NUT (OR MS21042-3)
8	18	18			MS21042L4	NUT (OR MS21042-4)
	4	4			MS21042L5	NUT (OR MS21042-5)

• COPYRIGHT © 2004 BY DART AEROSPACE LTD •

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.


Revision: B

Date: 10.06.15


DART

REFERENCE ONLY

DESIGN MB	DRAWN BY MB	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA	
CHECKED 	APPROVED 	DRAWING NO. D3436	REV. A SHEET 1 OF 4
DATE 05.04.28	TITLE MAINTENANCE STEP		SCALE 1:4
A	05.04.28	NEW ISSUE	

**NOTES:**

- 1) POSITION PARTS AS PER JIGS DT8772 AND DT8773
- 2) WELD PER DART QSI 004
- 3) FILLET BOTH TOP AND BOTTOM EDGES OF CLAMP ALONG 2.38 I.D. SECTION TO 0.03 RADIUS TO PREVENT SCORING AND SCRATCHING OF SKID CROSS TUBE
- 4) FINISH: POWDER COAT WHITE GLOSS (4.3.5.2) PER DART QSI 005 4.3
- 5) APPLY BLACK ANTI-SKID PAINT AS SHOWN PER DART QSI 005 4.4
- 6) TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED
- 7) ALL DIMENSIONS ARE IN INCHES

RELEASED05.05.27 

COPYRIGHT © 2005 BY DART AEROSPACE LTD.

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.